

**Himachal Pradesh
Public Works Department**


No. SD-III-CB-WA-Structure Stability /2024- **637-38** Dated **10/4/2025**

To


✓ The Principal,
DAV Sr. Sec. School,
Lakkar Bazar Shimla.

Subject: Regarding issuance of Building Stability Certificate.

With reference to above cited subject, it is informed that the concerned Assistant Engineer, alongwith Junior Engineer has inspected the building on dated 07-04-2025. The building cannot be verified structurally. However, the building appears to be visually safe for occupancy. Hence, the building structure stability cannot be ascertained. But the said building visually ~~of the building~~ seems fit for habitation and running school activities for the year 2025-26 under normal condition.


Executive Engineer,
Shimla Division No.III,
HP.PWD. Shimla-3

Copy forwarded to the Assistant Engineer, Medical Collage Sub Division, HP. PWD., and Shimla with reference to his office letter No.SSD-VII-Building Safety/2024- 14 dated 05-04-2025 for information.


Executive Engineer,
Shimla Division No.III,
HP.PWD, Shimla-3